



UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

Page 1 of 3

NO. N90-17-4-2

To the following Permittee or Operator:

Name Genual Coal Company
 Mine Crandall Canyon Mine ☐ Surface ☒ Underground ☐ Other
 County Emery State ut Telephone 687-9813
 Mailing Address PO Box 1201 Huntington, Utah 84528
 State Permit No. ACT/015/032
 Ownership Category ☐ State ☒ Federal ☐ Fee ☐ Mixed
 Date of inspection SEPTEMBER 5, 1990
 Time of inspection 8:30 ☒ a.m. ☐ p.m. to 8:30 ☐ a.m. ☒ p.m.
 Operator Name (other than Permittee) _____
 Mailing Address _____

Under authority of the Utah Coal Mining and Reclamation Act, Section 40-10-1 et seq., Utah Code Annotated, 1953, the undersigned authorized representative of the Division of Oil, Gas & Mining has conducted an inspection of above mine on above date and has found violation(s) of the act, regulations or required permit condition(s) listed in attachment(s). This notice constitutes a separate Notice of Violation for each violation listed.

You must abate each of these violations within the designated abatement time. You are responsible for doing all work in a safe and workmanlike manner.

The undersigned representative finds that cessation of mining is ☐ is not ☒ expressly or in practical effect required by this notice. For this purpose, "mining" means extracting coal from the earth or a waste pile, and transporting it within or from the mine site.

This notice shall remain in effect until it expires as provided on reverse side of this form, or is modified, terminated or vacated by written notice of an authorized representative of the director of the Division of Oil, Gas & Mining. Time for abatement may be extended by authorized representative for good cause, if a request is made within a reasonable time before the end of abatement period.

Date of service/mailling Sept 5, 1990

Time of service/mailling 5:35 ☐ a.m. ☒ p.m.

Jim Pruitt
 Permittee/Operator representative

Safety Director
 Title

[Signature]
 Signature

Lynn Kunzler
 Division of Oil, Gas & Mining representative

Senior Reclamation Biologist
 Title

[Signature]
 Signature

#17
 Identification Number

SEE REVERSE SIDE

WHITE-DOGM YELLOW-OSM PINK-PERMITTEE/OPERATOR GOLDENROD-NOV FILE

notice of violation



NOTICE OF VIOLATION NO. N90-17-4-2

Violation No. 1 of 2

Nature of violation

Failure to maintain Diversion Ditches.

Provisions of act, regulations or permit violated

R614-301-742, 423, 3

R614-300-142, -143

Portion of operation to which notice applies

DD-8 diversion along portal access road,

DD-4 diversion affected by retaining wall construction

Remedial action required (including any interim steps)

Re-establish ditch along access road, (DD-8)

Re-establish ditch below retaining wall (DD-4)

Abatement time (including interim steps)

By 4:00 PM on October 1, 1990



NOTICE OF VIOLATION NO. N90-17-4-2

Violation No. 2 of 2

Nature of violation

Failure to construct facilities in accordance to
approved plan.

Provisions of act, regulations or permit violated

R 614-300-142

Portion of operation to which notice applies

Culvert 3-C

Remedial action required (including any interim steps)

1. Demonstrate existing culvert is adequate to pass
design flow and amend plan to show correct
culvert sizing, OR

2. replace existing 12" culvert with 24" designed culvert

Abatement time (including interim steps)

By 4:00 PM On October 1, 1990